



# Surface Testing – SARS-CoV-2 Report

Last updated: 7/9/2020				
Building Information		Company Name		
		Facility Name		
Sample Name	Sample Information	Collection Date	Test Date	COVID-19 Results
20128AC01289-1	AL MED ROOM	-	9-Jul-2020	Negative
20128AC01289-2	AL ELEVATOR BUTTON	-	9-Jul-2020	Borderline
20128AC01289-3	MC MED ROOM	-	9-Jul-2020	Negative
20128AC01289-4	MC COMMON AREA CHAIR	-	9-Jul-2020	Negative
20128AC01289	AL MED ROOM AL ELEVATOR BUTTON MC MED ROOM MC COMMON AREA CHAIR	-	8-Jul-2020	Inconclusive
20128AC01290	ADMIN EMPLOYEE TIME CARD AREA FULL COUNT SCREEN B WING ELEVATOR BUTTON ADMIN DOOR HANDLE	-	8-Jul-2020	Negative
20128AC01167-1	4TH FLOOR SITTING AREA LIBRARY	7/2/20	5-Jul-2020	Negative
20128AC01167-2	2ND RESIDENT RELATIONS DOOR	7/2/20	5-Jul-2020	Negative
20128AC01167-3	1ST CONCIERGE COUNTER	7/2/20	5-Jul-2020	Negative
20128AC01167-4	1ST FLOOR EMPLOYEE TEMP BREAKROOM	7/2/20	5-Jul-2020	Negative
20128AC01167	4TH FLOOR SITTING AREA LIBRARY 2ND RESIDENT RELATIONS DOOR 1ST CONCIERGE COUNTER 1ST FLOOR EMPLOYEE TEMP BREAKROOM	7/2/20	3-Jul-2020	Inconclusive
20128AC01168	AL MED ROOM	7/2/20	3-Jul-2020	Negative

	AL BREAKTABLE IN DR MC ME ROOM MC LAUNDRY ROOM			
20128AC01165	AL FRONT ENTTRANCE DOOR HANDLE AL FRONT EMPLOYEE ENTRANCE MC BATHROOM MC KITCHEN FRIG HANDLE	6/30/20	1-Jul-2020	Negative
20128AC01166	LOOKING GLASS KITCHEN OUTSIDE DELIVERY DOOR RECEPTIONIST COUNTER FULL COUNT MACHINE	6/30/20	1-Jul-2020	Negative
20128AC01014	Door Handle To Outside Patio 3rd Floor Mens Bathroom Looking Glass POS Register Fancho	6/25/20	26-Jun-2020	Negative
20128AC01015	AL Front Door Handle AL Doorbell Switch MC Bathroom #1 Door Handle MC Chart Room Door Handle	6/25/20	26-Jun-2020	Negative
20128AC01012	AL Elevator Button and Keypad MC Handrail Outside Room 101 MC Medroom Counter MC Chairs Common Area	6/23/20	24-Jun-2020	Negative
20128AC01017	IL Admin Door Handle IL Food Cart Handle IL Elevator Button IL Full Court Screen	-	24-Jun-2020	Negative
20128AC00930	MC LAUNDRY WASHERS MC ACTIVITIES KEYBOARD AL CHART ROOM DRAWER HANDLE AL MED STORAGE ROOM DOOR HANDLE	6/17/20	18-Jun-2020	Negative
20128AC00982	RECEPTIONIST COUNTER FULL COUNT MONITOR/CHAIR FANCHO SMALL TABLE 4TH FLOOR LAUNDRY ROOM WASHER	6/17/20	18-Jun-2020	Negative

20128AC00935	KITCHEN FRIDGE HANDLE FOOD PICKUP WARMING AREA KITCHEN HANDRAIL BY BILLARD AREA PLASTIC DISHRACK - DISHWASHER	6/16/20	18-Jun-2020	Negative
20128AC00983	AL FRONT ENTRY INSIDE DOOR HANDLES KITCHEN DOOR HANDLE AL SIDE DOOR HANDLE STAIRWAY RAIL	6/16/20	18-Jun-2020	Negative
20128AC00895	AL MED ROOM KEYPAD AL MED ROOM SINK HANDLE MC MED ROOM KEYPAD MC MED ROOM COMPUTER MOUSE6/11	6/12/20	12-Jun-2020	Negative
20128AC00894	2ND FLOOR LAUNDRY WASHER 1ST FLOOR WOMENS PUBLIC BATHROOM 4TH FLOOR RESIDENT COMPUTER KEYBOARD 3RD FLOOR LAUNDRY ROOM CHAIR	6/11/20	12-Jun-2020	Negative
20128AC00888-1	TRIPLE SINK WATER HANDLES	6/9/20	11-Jun-2020	Negative
20128AC00888-2	UTENSIL DRAWER HANDLE	6/9/20	11-Jun-2020	Negative
20128AC00888-3	KITCHE FAUCET SINK HANDLE	6/9/20	11-Jun-2020	Negative
20128AC00888-4	MEDROOM SINK FAUCET HANDLE	6/9/20	11-Jun-2020	Inconclusive
20128AC00888	TRIPLE SINK WATER HANDLES UTENSIL DRAWER HANDLE KITCHE FAUCET SINK HANDLE MEDROOM SINK FAUCET HANDLE	6/9/20	10-Jun-2020	Inconclusive
20128AC00889	2ND FLOOR LADIES ROOM 2ND FLOOR LAUNDRY 1ST FLOOR WOMENS LOCKER ROOM TOILET 1ST FLOOR STORE	6/9/20	10-Jun-2020	Negative
20128AC00516	Spa Room MC Door	6/3/20	5-Jun-2020	Negative
20128AC00516	Breakroom	6/3/20	5-Jun-2020	Positive

				High
20128AC00516	Elevator Button	6/3/20	5-Jun-2020	Negative
20128AC00516	MC Chartroom	6/3/20	5-Jun-2020	Negative
20128AC00514	Login Keyboard Looking Glass Main Kitchen Door Handle Deliveries Door Kitchen	6/3/20	4-Jun-2020	Negative
20128AC00516	Spa Room MC Door Breakroom Elevator Button MC Chartroom	6/3/20	4-Jun-2020	Positive Med
20128AC00517	OUTSIDE DOOR HANDLE ENT	6/2/20	4-Jun-2020	Inconclusive
20128AC00517	PUBLIC BATHROOM AL	6/2/20	4-Jun-2020	Positive Low
20128AC00517	EMPLOYEE TIME CLOCK KEYBOARD	6/2/20	4-Jun-2020	Positive High
20128AC00517	MC BATHROOM TOILET HANDLE	6/2/20	4-Jun-2020	Positive High
20128AC00515	EMPLOYEE TIME CLOCK KEYBOARD	6/2/20	4-Jun-2020	Inconclusive
20128AC00515	OFFICE DOOR HANDLE	6/2/20	4-Jun-2020	Negative
20128AC00515	LOOKING GLASS SITTING AREA	6/2/20	4-Jun-2020	Inconclusive
20128AC00515	FULL COUNT SCREEN	6/2/20	4-Jun-2020	Negative
20128AC00517	Outside door handle ent Public bathroom AL Employee time clock keyboard MC bathroom toilet handle	6/2/20	6/3/20	Positive High
20128AC00515	Employee time clock keyboard Office door handle Looking glass sitting area Full count screen	6/2/20	6/3/20	Inconclusive
20128AC00237	3rd floor women's bathroom 3rd floor private dining room 4th floor laundry	5/27/20	5/29/20	Negative

	4th floor HVAC supply register			
20128AC00287	MC spa room MC hair salon AL chart room AL laundry room	5/27/20	5/29/20	Negative
20128AC00311	IL looking glass IL door handle from recep office IL bathroom men's IL delivery door kitchen	5/26/20	5/27/20	Negative
20128AC00312	Bathroom AL Entrance dr AL Elevator button MC	5/26/20	5/27/20	Negative
20128AC00127	Looking glass chair Employee time clock Public bathroom 2nd floor women's Elevator button 2nd floor	5/20/20	5/21/20	Negative
20128AC00206	Women's locker room Store Library gym	5/20/20	5/21/20	Negative
20128AC00009	AL main entrance AL elevator button AL chartroom chair AL bathroom toilet handle/door handle	5/19/20	5/20/20	Negative
20128AC00121	MC bathroom (primary) door handle MC chartroom door handle MC breakroom chair/table MC outside door handle	5/19/20	5/20/20	Negative
20128AC00045	Timeclock mouse 2nd floor bathroom doorknob C wing elevator button Kitchen door	5/13/20	5/14/20	Negative
20128AC00081	Admin doorknob to D wing receptionist computer IL Air intake lobby IL full count screen Fancho IL	5/13/20	5/14/20	Negative

**Legal disclaimer:** This report does not constitute legal advice or clinical representation of the presence or absence of the virus COVID-19. This report cannot be used to rule out the presence of virus in a facility. It provides only the results from the surfaces tested. Positive test results indicate the presence of viral particles and may indicate that the surface was contaminated by contact or proximity with an infected person. Enviral Tech encourages individuals and organizations to take universal precautions based on the most current advice from public health officials. For additional information, please see <https://www.cdc.gov/coronavirus/2019-nCoV/index.html>.

## Explanation of Results

**Negative** No SARS-CoV-2 Virus was detected

**Positive** PCR Testing shows presence of virus in customer sample  
Low Positive – between 100 - 200 viral particles  
Medium Positive - between 200 - 1000 viral particles  
High Positive - >1000 viral particles

**Inconclusive** In a primary test, COVID-19 signal is present, but below the theoretical limit of reliable detection. In the case of pooled samples, there is a chance that individual swabs could be positive

**Borderline** In a secondary test, evidence supports the presence of COVID-19 virus in the sample. However, the level of virus particles is below the number of molecules for which a second test is certain to produce the same answer

Note: A positive result is given only if all of the following is true:

1. The positive control tests positive,
  2. The negative control tests negative,
  3. There is a confirmed sampling using our internal control, and
  4. The test of the sample shows the presence of virus
- If either control sample fails, all tests are invalidated and Enviral Tech will rerun the samples free of charge.
  - If the internal control failed, Enviral Tech will rerun the sample one time free of charge.
  - If the internal control fails a second time, the conclusion is that no sample was taken, or that the sample includes environmental contaminants that interfere with the test. We would recommend ordering a new sample kit to retest.

